


鉄 + JISナベ小ねじ

00000010

鉄



| ねじの呼び (d) | ピッチP | 十字穴の番号 | dk | | k | | m | q(十字穴深さ) |
|--------------|------|--------|------|--------|------|-------|-----|-----------|
| | | | 基準寸法 | 許容差 | 基準寸法 | 許容差 | | |
| M3 | 0.6 | 2 | 5.5 | 0 | 2 | ±0.15 | 3.6 | 1.43 0.86 |
| M4 | 0.75 | | 7 | -0.5 | 2.6 | | 4.2 | 2.03 1.45 |
| M5 | 0.9 | | 9 | 0 -0.6 | 3.3 | | 4.9 | 2.73 2.14 |

| M3.0 | | | | | | | | |
|------|---------|----|----|----|------|------|----|----|
| 大きさ | 入数 | 単位 | ヨコ | コロ | アーマー | クイック | 三面 | 四面 |
| 4 | 3000×20 | | ● | ● | ● | ● | ● | ● |
| 5 | 3000×20 | | ● | ● | ● | ● | ● | ● |
| 6 | 2500×20 | | ● | ● | ● | ● | ● | ● |
| 8 | 2200×20 | | ● | ● | ● | ● | ● | ● |
| 9 | 2000×20 | | ● | ● | ● | ● | ● | ● |
| 10 | 2000×20 | | ● | ● | ● | ● | ● | ● |
| 12 | 2500×14 | | ● | ● | ● | ● | ● | ● |
| 14 | 2200×14 | | ● | ● | ● | ● | ● | ● |
| 15 | 2000×14 | | ● | ● | ● | ● | ● | ● |
| 16 | 2000×14 | | ● | ● | ● | ● | ● | ● |
| 18 | 1600×14 | | ● | ● | ● | ● | ● | ● |
| 20 | 1600×14 | | ● | ● | ● | ● | ● | ● |
| 22 | 1500×14 | | ● | ● | ● | ● | ● | ● |
| 25 | 1400×14 | | ● | ● | ● | ● | ● | ● |
| 28 | 1200×14 | | ● | ● | ● | ● | ● | ● |
| 30 | 1000×14 | | ● | ● | ● | ● | ● | ● |
| 35 | 700×14 | | ● | ● | ● | ● | ● | ● |
| 40 | 600×14 | | ● | ● | ● | ● | ● | ● |


| M4.0 | | | | | | | | |
|------|---------|----|----|----|------|------|----|----|
| 大きさ | 入数 | 単位 | ヨコ | コロ | アーマー | クイック | 三面 | 四面 |
| 5 | 2500×14 | | ● | ● | ● | ● | ● | ● |
| 6 | 2200×14 | | ● | ● | ● | ● | ● | ● |
| 8 | 2000×14 | | ● | ● | ● | ● | ● | ● |
| 10 | 1600×14 | | ● | ● | ● | ● | ● | ● |
| 12 | 1500×14 | | ● | ● | ● | ● | ● | ● |
| 14 | 1200×14 | | ● | ● | ● | ● | ● | ● |
| 15 | 1200×14 | | ● | ● | ● | ● | ● | ● |
| 16 | 1000×14 | | ● | ● | ● | ● | ● | ● |
| 18 | 1000×14 | | ● | ● | ● | ● | ● | ● |
| 20 | 900×14 | | ● | ● | ● | ● | ● | ● |
| 22 | 800×14 | | ● | ● | ● | ● | ● | ● |
| 25 | 700×14 | | ● | ● | ● | ● | ● | ● |
| 30 | 600×14 | | ● | ● | ● | ● | ● | ● |
| 35 | 500×14 | | ● | ● | ● | ● | ● | ● |
| 40 | 600×10 | | ● | ● | ● | ● | ● | ● |
| 45 | 500×10 | | ● | ● | ● | ● | ● | ● |
| 50 | 450×10 | | ● | ● | ● | ● | ● | ● |
| 55 | 400×10 | | ● | ● | ● | ● | ● | ● |
| 60 | 300×10 | | ● | ● | ● | ● | ● | ● |
| 65 | 300×10 | | ● | ● | ● | ● | ● | ● |
| 70 | 300×14 | | ● | ● | ● | ● | ● | ● |

| M5.0 | | | | | | | | |
|------|---------|----|----|----|------|------|----|----|
| 大きさ | 入数 | 単位 | ヨコ | コロ | アーマー | クイック | 三面 | 四面 |
| 6 | 1000×14 | | ● | ● | ● | ● | ● | ● |
| 8 | 1000×14 | | ● | ● | ● | ● | ● | ● |
| 10 | 900×14 | | ● | ● | ● | ● | ● | ● |
| 12 | 800×14 | | ● | ● | ● | ● | ● | ● |
| 14 | 800×14 | | ● | ● | ● | ● | ● | ● |
| 15 | 700×14 | | ● | ● | ● | ● | ● | ● |
| 16 | 700×14 | | ● | ● | ● | ● | ● | ● |
| 18 | 600×14 | | ● | ● | ● | ● | ● | ● |
| 20 | 500×14 | | ● | ● | ● | ● | ● | ● |
| 22 | 700×12 | | ● | ● | ● | ● | ● | ● |
| 25 | 700×10 | | ● | ● | ● | ● | ● | ● |
| 28 | 600×10 | | ● | ● | ● | ● | ● | ● |
| 30 | 600×10 | | ● | ● | ● | ● | ● | ● |
| 35 | 500×10 | | ● | ● | ● | ● | ● | ● |
| 40 | 400×10 | | ● | ● | ● | ● | ● | ● |
| 45 | 350×10 | | ● | ● | ● | ● | ● | ● |
| 50 | 300×10 | | ● | ● | ● | ● | ● | ● |
| 55 | 250×10 | | ● | ● | ● | ● | ● | ● |
| 60 | 230×10 | | ● | ● | ● | ● | ● | ● |
| 65 | 200×10 | | ● | ● | ● | ● | ● | ● |
| 70 | 200×14 | | ● | ● | ● | ● | ● | ● |

ステンレス + ナベ小ねじ JIS-1996

00020060

ステンレス



| ねじの呼び (d) | ピッチP | H形 十字穴の番号 | dk | | k | | m |
|--------------|------|--------------|------|---------|------|---------|-----|
| | | | 基準寸法 | 許容差 | 基準寸法 | 許容差 | |
| M4 | 0.7 | 2 | 8 | 0 -0.36 | 3.1 | 0 -0.18 | 4.4 |

M4.0

| 大きさ | 入数 | 単位 |
|-----|---------|----|
| 6 | 1000×24 | ● |
| 8 | 1000×24 | ● |
| 10 | 1000×18 | ● |
| 12 | 1000×18 | ● |
| 15 | 500×24 | ● |
| 16 | 500×24 | ● |
| 20 | 500×24 | ● |
| 25 | 500×18 | ● |