

# ⊕ ナベ小ねじ(半ねじ)(ねじ部50)



00000500


鉄

00010500

黄銅

00020500

ステンレス



ねじの呼び (d)	ピッチ P	十字穴の番号	dk		K		m
			基準寸法	許容差	基準寸法	許容差	
M2.6	0.45	1	4.5	0 -0.4	1.7	±0.1	2.6
M3	0.50	2	5.5	0 -0.5	2.0	±0.15	3.6
M4	0.70		7	2.6	4.2		
M5	0.80		9	0 -0.6	3.3		4.9
M6	1.00	3	10.5	0 -0.7	3.9	±0.2	6.3
M8	1.25		14	0 -0.8	5.2		7.8

M2.6				
長さ	入り数	鉄		
		生地	クロメート	三価ホワイト
60	500×14	●	●	●

M3.0										
長さ	入り数	鉄								ステンレス
		生地	クロメート	三価ホワイト	三価ブラック	ニッケル	クロム	亜鉛黒	グリーン	
55	600×10	●	●	●	●	●	●	●	●	●
58	500×10	●	●	●	●	●	●	●	●	●
60	500×10	●	●	●	●	●	●	●	●	●
65	500×10	●	●	●	●	●	●	●	●	●
68	800×10	●	●	●	●	●	●	●	●	●
70	800×10	●	●	●	●	●	●	●	●	●
72	700×10	●	●	●	●	●	●	●	●	●
75	700×10	●	●	●	●	●	●	●	●	●
80	500×14	●	●	●	●	●	●	●	●	●
85	500×14	●	●	●	●	●	●	●	●	●
90	500×14	●	●	●	●	●	●	●	●	●
92	400×14	●	●	●	●	●	●	●	●	●
95	400×14	●	●	●	●	●	●	●	●	●
97	400×14	●	●	●	●	●	●	●	●	●
100	400×14	●	●	●	●	●	●	●	●	●
102	500×10	●	●	●	●	●	●	●	●	●
105	500×10	●	●	●	●	●	●	●	●	●
110	500×10	●	●	●	●	●	●	●	●	●
115	500×10	●	●	●	●	●	●	●	●	●
120	500×10	●	●	●	●	●	●	●	●	●
120	600×8	●	●	●	●	●	●	●	●	●
122	500×10	●	●	●	●	●	●	●	●	●
125	500×10	●	●	●	●	●	●	●	●	●
125	600×8	●	●	●	●	●	●	●	●	●
130	600×8	●	●	●	●	●	●	●	●	●
135	600×8	●	●	●	●	●	●	●	●	●
140	600×8	●	●	●	●	●	●	●	●	●
145	600×8	●	●	●	●	●	●	●	●	●
150	600×8	●	●	●	●	●	●	●	●	●
155	600×8	●	●	●	●	●	●	●	●	●
160	600×8	●	●	●	●	●	●	●	●	●
165	600×6	●	●	●	●	●	●	●	●	●
170	600×6	●	●	●	●	●	●	●	●	●
175	600×6	●	●	●	●	●	●	●	●	●
180	600×6	●	●	●	●	●	●	●	●	●
190	600×6	●	●	●	●	●	●	●	●	●
200	600×6	●	●	●	●	●	●	●	●	●
210	600×6	●	●	●	●	●	●	●	●	●
250	600×4	●	●	●	●	●	●	●	●	●